



## VIN.DOCTOR VEHICLE HISTORY REPORT

# 2020 BMW X3

VIN 5UXTY3C04LLU69645

Generated: 09 Aug 2022



+ 39 more



**Odometer records**  
No problems found



**Vehicle damages**  
3 problems found



**Accidents**  
No problems found



**Salvage records**  
No problems found



**Theft records**  
No problems found



**Lien / impound / export records**  
No problems found



**Junk / salvage / insurance records**  
10 problems found



**Other title brands check**  
2 problems found



**Safety recall campaigns**  
19 problems found



**Title history**  
4 records found



**Sales history**  
No records found



**Number of owners**  
4 owners



## Vehicle details



**Year**  
2020



**Make**  
BMW



**Model**  
X3



**Trim**  
SDrive30i



**Engine**  
2.0-L L-4 DOHC 16V



**Country**  
United States



**Body**  
No data



**Steering type**  
Rack & Pinion



**Anti-brake system**



**Fuel type**



**Fuel capacity**



**Weight**

4-Wheel ABS

Regular

17.20 gallons

6000 pounds



**Height**

66.00 inches



**Length**

185.90 inches



**Width**

74.40 inches



**Standard seating**

5



**Optional seating**

No data



**Highway mileage**

29 miles/gallon



**City mileage**

25 miles/gallon



**Invoice price**

\$39 515



**MSRP**

\$41 950



## Ownership history



**1 owner**

Last odometer check:  
105 miles

Year of purchase:  
2020

Estimated length of use:  
1m



**2 owner**

Last odometer check:  
3000 miles

Year of purchase:  
2020

Estimated length of use:  
1 y 8m



**3 owner**

Last odometer check:  
3670 miles

Year of purchase:  
2021

Estimated length of use:  
4m



**4 owner**

Last odometer check:  
4068 miles

Year of purchase:  
2022

Estimated length of use:  
N/A



## Odometer check

### Actual

The true mileage for the vehicle. The odometer has not been tampered with, reached its mechanical limits, or been altered.



No problems found

### Not actual

The odometer reading is known to be other than the true mileage for the vehicle.



No problems found

**Tampering verified**

Odometer tampering verified - The odometer reading is known to be other than the true mileage for the vehicle, due to tampering.



No problems found

**Exempt from odometer disclosure**

The vehicle falls within criteria that allow it to change ownership without disclosure of the odometer reading.



No problems found

**Exceeds mechanical limits**

The odometer reading is less than the true mileage of the vehicle because the odometer can not display the total number of true miles.



No problems found

**May be altered**

The titling authority has reason to believe that the odometer reading does not reflect the true mileage of the vehicle because of an alteration to the odometer.



No problems found

**Replaced**

The odometer in the vehicle is not the odometer put in the vehicle when manufactured.



No problems found

**Reading at time of renewal**

The odometer reading was recorded when the registration was renewed.



No problems found

**Discrepancy**

The titling authority has reason to believe that the odometer reading does not reflect the true mileage of the vehicle because of known previous recorded values of odometer for the vehicle.



No problems found

**Call title division**

The titling authority knows of some problem with the odometer reading that it cannot print on a title. Titling authority will discuss the problem (manual process) with authorized inquirers.



No problems found

**Exceeds mechanical limits rectified**

A state other than the brander corrected brand 72.



No problems found



## Title history

records found: 4

### CURRENT TITLE INFORMATION


TITLE ISSUE DATE	STATE	MILEAGE
22 Apr 2022	CA	4068 miles

### HISTORICAL TITLE INFORMATION

TITLE ISSUE DATE	STATE	MILEAGE
30 Nov 2021	CA	3670 miles
10 Mar 2020	AZ	3000 miles
13 Jan 2020	AZ	105 miles



## Mileage / year history



# Junk / salvage / insurance records

problems reported: 10

DATE	REPORTING ENTITY	RECORD TYPE	DISPOSITION	FOR EXPORT
20 May 2022	Copart Inc. Dallas, TX	Junk And Salvage	TO BE DETERMINED	N
20 May 2022	Copart Inc. Dallas, TX	Junk And Salvage	SOLD	Y
22 Feb 2022	STATE FARM INSURANCE Bloomington, IL	Insurers	N/A	N/A
22 Feb 2022	IAA WESTCHESTER, IL	Junk And Salvage	TO BE DETERMINED	N
22 Feb 2022	IAA WESTCHESTER, IL	Junk And Salvage	SOLD	N
22 Feb 2022	IAA WESTCHESTER, IL	Junk And Salvage	SOLD	N
24 Jul 2020	IAA WESTCHESTER, IL	Junk And Salvage	SOLD	N
14 Feb 2020	Copart, Inc. Dallas, TX	Junk And Salvage	TO BE DETERMINED	N
14 Feb 2020	Copart, Inc. Dallas, TX	Junk And Salvage	SOLD	N
13 Feb 2020	GEICO CASUALTY COMPANY TUCSON, AZ	Insurers	N/A	N/A



## Theft records

✓ No records found



## Lien / impound / export records

✓ No records found



## Accident records

✓ No records found






## Salvage records

✓ No records found



## Vehicle damages



-  1. Front end
-  2. Left side
-  3. Side



# Other title brands check

problems reported: 2

## Salvage: damage or not specified

Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values. Salvage—damage or not specified also includes any vehicle to which an insurance company acquires owner- ship pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.



**Problem found**

**Date:** 22 Apr 2022

**Brander:** CALIFORNIA (State)

**Disposition:** N/A



**Problem found**

**Date:** 10 Mar 2020

**Brander:** ARIZONA (State)

**Disposition:** N/A

## Rebuilt

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).



**Problem found**

**Date:** 30 Nov 2021

**Brander:** CALIFORNIA (State)

**Disposition:** N/A

## Flood damage

A flood damage record means the vehicle damaged by freshwater flood (or it is unknown whether the damage was caused by fresh water or salt water).



No problems found

## Fire damage

A fire damage record means that the vehicle was damaged by fire.



No problems found

## Hail damage

Vehicle damaged by hail.



No problems found

## Salt water damage

Vehicle damaged by saltwater flood.



No problems found

## Vandalism

Vehicle damaged by vandals.



No problems found

## Kit

A Vehicle that has been built by combining a chassis with a different (non-matching VIN) frame, engine, and body parts. The VIN on the chassis is used as the vehicle's VIN.



No problems found

## Dismantled

The vehicle can only be sold as parts and can not be legally driven.



No problems found

**Junk**

The vehicle is incapable of safe operation for use on the roads or highways and has no resale value except as a source of parts or scrap, or the vehicle's owner has irreversibly designated the vehicle as a source of parts or scrap. This vehicle shall never be titled or registered. Also known as non-repairable, scrapped, or destroyed.

✓ No problems found

**Reconstructed**

A vehicle that has been permanently altered from original construction by removing, adding, or substituting major components.

✓ No problems found

**Test Vehicle**

The vehicle is built and retained by the manufacturer for testing.

✓ No problems found

**Refurbished**

Any vehicle modified by the installation of a new cab and chassis for the existing coach which has been renovated, resulting in a vehicle of greater value or a vehicle with a new style.

✓ No problems found

**Collision**

Vehicle damaged by collision.

✓ No problems found

**Salvage retention**

The vehicle is branded salvage and is kept by the owner.

✓ No problems found

**Prior taxi**

Vehicle previously registered as a taxi.

✓ No problems found

**Prior police**

Vehicle previously registered as a police vehicle.

✓ No problems found

**Original taxi**

Vehicle is currently registered as a taxi.

✓ No problems found

**Original police**

Vehicle is currently registered as a police vehicle.

✓ No problems found

**Remanufactured**

Vehicle was reconstructed by the manufacturer.

✓ No problems found

**Gray market**

Vehicle was manufactured for use outside of the United States and has been brought into the United States. Brand '22' has been replaced by brands '45' and '46', as of 6/25/01.

✓ No problems found

**Warranty return**

Vehicle returned to the manufacturer because of a breach in the warranty.

✓ No problems found

**Antique**

The vehicle is over 50 years old.

✓ No problems found

**Classic**

The vehicle is over 20 years old and adheres to other jurisdiction-specific criteria, e.g., vehicle make, condition, etc.

✓ No problems found



**Agricultural vehicle**

The vehicle will primarily be operated on private roads for agricultural purposes.



No problems found

**Logging vehicle**

The vehicle will primarily be operated on private roads for logging purposes.



No problems found

**Street rod**

The vehicle has been modified to not conform with the manufacturer's specifications, and the modifications adhere to jurisdiction-specific criteria.



No problems found

**Vehicle contains reissued vin**

The chassis VIN has been reissued, i.e. the same VIN is reused.



No problems found

**Replica**

A vehicle with a body built to resemble and be a reproduction of another vehicle of a given year and given manufacturer.



No problems found

**Totaled**

A vehicle that is declared a total loss by a jurisdiction or an insurer that is obligated to cover the loss or that the insurer takes possession of or title to.



No problems found

**Owner retained**

A vehicle that has been declared by the insurance company to be a total loss but the owner maintains possession and ownership of the vehicle.



No problems found

**Bond posted**

The insurance company has issued a bond on the vehicle because the ownership of the vehicle cannot be proven; this allows the vehicle to be sold and titled. Note: This brand is not valid after January 17, 2003.



No problems found

**Memorandum copy**

The title document is a facsimile title and not the active (original or duplicate) title document.



No problems found

**Parts only**

The vehicle may only be used for parts. This code is no longer used, use '07 - Dismantled'.



No problems found

**Recovered theft**

The vehicle was previously titled as salvage due to theft. The Vehicle has been repaired and inspected (or complied with other jurisdiction procedures) and may be legally driven.



No problems found

**Undisclosed lien**

The vehicle has entered the titling jurisdiction from a jurisdiction that does not disclose lien-holder information on the title. The titling jurisdiction may issue a new title without this brand if no notice of a security interest in the vehicle is received, within a jurisdiction defined timeframe. Note: This brand is not valid after January 17, 2003.



No problems found

**Prior owner retained**

A vehicle that was previously branded owner retained and was sold. The new owner's title contains this brand.



No problems found

**Vehicle non-conformity uncorrected**

A non-safety defect reported to the jurisdiction by the vehicle manufacturer remains uncorrected.

✓ No problems found

**Vehicle non-conformity corrected**

A non-safety defect reported to the jurisdiction by the vehicle manufacturer has been corrected.

✓ No problems found

**Vehicle safety defect uncorrected**

A safety defect reported to the jurisdiction by the vehicle manufacturer remains uncorrected.

✓ No problems found

**Vehicle safety defect corrected**

A safety defect reported to the jurisdiction by the vehicle manufacturer has been corrected.

✓ No problems found

**VIN replaced**

VIN replaced by a new state assigned VIN. A title should not be issued for the VIN. This brand can be issued for rebuilt vehicles.

✓ No problems found

**Gray market: non-compliant**

Vehicle was manufactured for use outside the United States and has been brought into the United States. The vehicle is not in compliance with applicable federal standards.

✓ No problems found

**Gray market: compliant**

Vehicle was manufactured for use outside the United States and has been brought into the United States. The vehicle is in compliance with applicable federal standards.

✓ No problems found

**Manufacturer buy back**

A vehicle that has been bought back by the manufacturer under jurisdiction-defined regulations or laws, such as lemon laws. For example, the manufacturer could be obligated to buy back the vehicle when a specified number of repair attempts fails to correct a major problem on a new vehicle, or if a new vehicle has been out of service for repair for the same problem for a cumulative period of 30 days or more, within one year of purchase.

✓ No problems found

**Former rental**

Vehicle has been used as a rental vehicle.

✓ No problems found

**Salvage: stolen**

Any vehicle the reporting jurisdiction considers salvage because an insurance company has acquired ownership pursuant to a settlement based on the theft of the vehicle.

✓ No problems found

**Salvage: reasons other than damage or stolen**

Any vehicle the reporting jurisdiction considers salvage based on criteria, such as abandonment, not covered by the Salvage-- Damage or Not Specified and Salvage-- Stolen brands. Note.--Percent of damage is not reported with brand code 50.

✓ No problems found

**Disclosed damage**

The vehicle has sustained damage to the extent that the damage is required to be disclosed under the jurisdiction's damage disclosure law.

✓ No problems found

**Prior non-repairable / repaired**

A vehicle constructed by repairing a vehicle that has been destroyed or declared to be non-repairable or otherwise declared to not be eligible for titling because of the extent of damage to the vehicle but has been issued a title pursuant to state law after falling within this criterion with this brand on the face of the certificate of title.

✓ No problems found

**Crushed**

The frame or chassis of the vehicle has been crushed or otherwise destroyed so that it is physically impossible to use it in constructing a vehicle.

✓ No problems found

**Hazardous**

The jurisdiction has determined that the vehicle has been contaminated by a 'hazardous substance' and is unsafe for use. Excluding flood damaged vehicles. A 'hazardous substance' is any substance that could diminish the safety of the vehicle or cause injury to its occupants. The 'hazardous substance' has one or more, but is not limited to the following intrinsic 'hazardous properties': explosiveness, flammability, ability to oxidize (accelerate a fire), human toxicity (acute or chronic), corrosiveness (to human tissue or metal), eco toxicity (with or without bioaccumulation), or capacity, on contact with air or water, to develop one or more of the above properties.

✓ No problems found

**Export only vehicle**

A salvage or junk vehicle determined for exportation outside of the United States and/or its territories, is not eligible for re-title/re-registration for on-road use in the United States.

✓ No problems found



## Sales history

DEALERS, EBAY, ETC - 0

✓ No records found

AUCTIONS SALES HISTORY - 20



23 Mar 2020




all photos

Lot number: [30597370](#)

Damage: Front end

SOLD

**\$4 450**

 29 Jul 2020




all photos

Lot number: [28141528](#) NEW LOT

NOT SOLD

Damage: Front end, Left side

**\$11 250**

 05 Aug 2020




all photos

Lot number: [28141528](#)

SOLD

Damage: Front end, Left side

**\$12 475**

 28 Apr 2022




all photos

Lot number: [32497081](#) NEW LOT

NOT SOLD

Damage: Front end, Left side

**\$10 050**

 05 May 2022




all photos

Lot number: [32497081](#)

SOLD

Damage: Front end, Left side

**\$10 025**

 31 May 2022



all photos

Lot number: [46625632](#) **NEW LOT**

Damage: Front end, Side

**NOT SOLD**

**\$18 800**



03 Jun 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

**NOT SOLD**

**\$18 800**



06 Jun 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

**NOT SOLD**

**\$19 000**



09 Jun 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

**NOT SOLD**

**\$19 000**



13 Jun 2022





all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 500**



20 Jun 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 700**



05 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 300**



08 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 300**



11 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 100**



14 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 100**



18 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$17 600**



21 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$17 600**



25 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 400**



28 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

NOT SOLD

**\$18 400**



29 Jul 2022



all photos

Lot number: [46625632](#)

Damage: Front end, Side

SOLD

**\$20 000**



## Safety recall campaigns

problems reported: 19



Date  
30 Sep 2020



Campaign  
20v598000



Components  
Back Over Prevention: Sensing  
System: Camera



#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020-2021 X3 Sdrive 30i, X3 Xdrive 30i, X3M 40i, X3 Xdrive 30e, X4 Xdrive 30i, X4M 40i, 530i, 540i, 540i Xdrive, M550i Xdrive, M5, 550e, 550e Xdrive, and 550e lperformance Vehicles. A Small Portion OF THE Rearview Image MAY BE Slightly Obscured. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rear Visibility."

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect And, IF Necessary, Program THE Rearview Camera With Updated Software. THE Recall Began November 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



#### Date

18 Aug 2020



#### Campaign

20v490000



#### Components

Electrical System:12v/24v/48v Battery

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2021 330e and X5 Xdrive45e, 2020-2021 X3 Xdrive30e, and 2020 Mini Countryman SE All4 Vehicles. Loose Welding Beads MAY Form A Conductive Path Between THE Hybrid Battery Cells Which Could Lead TO A Short-Circuit.

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect And, IF Necessary, Replace THE Battery Modules, Free OF Charge. BMW Issued Owners AN Interim Notification ON October 16, 2020. Although Potentially Affected BMW Owners Received Interim Owner Notification Letters, All Potentially Affected BMW Owner Vehicles Have Been Remedied; Therefore, BMW Final Owner Notification Letters Will NOT BE Necessary. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

A Short-Circuited Hybrid Battery MAY Increase THE Risk OF A Fire.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



#### Date

18 Mar 2020



#### Campaign

20v152000



#### Components

Electrical System: Instrument Cluster/Panel

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2020 X4 Xdrive30i and X4 M40i, and 2018-2020 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, and X3M Vehicles. THE Instrument Panel Casing MAY NOT Have Been Tightened Properly TO THE Passenger AIR Bag.

#### Remedy

BMW Will Notify Owners, and Dealers Will Replace THE Instrument Panel Casing, Free OF Charge. THE Recall Began MAY 15, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IN THE Event OF A Crash Necessitating AIR BAG Deployment, THE AIR BAG Could Damage THE Instrument Panel and Cause Small Pieces OF THE Panel TO Strike THE Driver or Other Occupants, Increasing THE Risk OF Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



#### Date

18 Mar 2020



#### Campaign

20v152000



#### Components

AIR Bags:frontal:passenger Side:inflator Module

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2020 X4 Xdrive30i and X4 M40i, and 2018-2020 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, and X3M Vehicles. THE Instrument Panel Casing MAY NOT Have Been Tightened Properly TO THE Passenger AIR Bag.

#### Remedy

BMW Will Notify Owners, and Dealers Will Replace THE Instrument Panel Casing, Free OF Charge. THE Recall Began MAY 15, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IN THE Event OF A Crash Necessitating AIR BAG Deployment, THE AIR BAG Could Damage THE Instrument Panel and Cause Small Pieces OF THE Panel TO Strike THE Driver or Other Occupants, Increasing THE Risk OF Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
29 Jul 2020



Campaign  
20v443000



Components  
Electrical System:software

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive40i, X3 Xdrive40i and X3m40i Vehicles. These Vehicles Were NOT Programmed With Rearview Camera Software During Assembly, Therefore, When THE Transmission IS Shifted TO Reverse, A Rearview Image IS NOT Displayed. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rearview Mirrors."

#### Remedy

BMW Will Notify Owners, and Dealers Will Program THE Affected Vehicles With Rearview Camera Software, Free OF Charge. THE Recall Began August 14, 2020. All Vehicles Have Been Remedied AS OF November 9, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

AN Inoperative Rearview Camera Display CAN Increase THE Risk OF A Crash When Reversing.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
29 Jul 2020



Campaign  
20v443000



Components  
Back Over Prevention: Sensing System: Camera

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive40i, X3 Xdrive40i and X3m40i Vehicles. These Vehicles Were NOT Programmed With Rearview Camera Software During Assembly, Therefore, When THE Transmission IS Shifted TO Reverse, A Rearview Image IS NOT Displayed. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rearview Mirrors."

#### Remedy

BMW Will Notify Owners, and Dealers Will Program THE Affected Vehicles With Rearview Camera Software, Free OF Charge. THE Recall Began August 14, 2020. All Vehicles Have Been Remedied AS OF November 9, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

AN Inoperative Rearview Camera Display CAN Increase THE Risk OF A Crash When Reversing.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
27 Sep 2019



Campaign  
19v684000



Components  
Back Over Prevention: Sensing System: Camera

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2018 540d, 2018-2020 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 530e, 530e Xdrive, X3 Sdrive, X3 Xdrive, X3 M40i, X3 M, and 2019-2020 X4 Xdrive, X4 M40i, X4 M, X7 Xdrive, X7 M50i, 740li, 740li Xdrive, 750li, 750li Xdrive, 8 Series Convertible and Coupe 840i, 840i Xdrive, M850i Xdrive, X5 Sdrive, X5 Xdrive, X5 M50i, X6 Xdrive, X6 M50i, 330i, 330i Xdrive, M340i, M340i Xdrive, Z4 Sdrive, Z4 M40i, 740le Xdrive and 745le Xdrive, 2018-2019 640i Xdrive Gran Turismo and Rolls-royce Phantom, 2019 M850i Xdrive Gran Coupe and Rolls-royce Cullinan and 2020 Toyota Supra Vehicles. THE Back-up Camera and Display Settings CAN BE Adjusted Such That THE Rear View Image IS NO Longer Visible and THE System Will Retain That Setting THE Next Time THE Vehicle IS Placed IN Reverse. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rearview Mirrors."

#### Remedy

BMW Will Notify Owners, and Dealers Will Update THE Back-Up Camera Software, Free OF Charge. THE Recall Began November 8, 2019. Owners MAY Contact BMW Customer Service AT 1-800-525-7417 or Rolls-royce AT 1-877-877-3735. Toyota Owners MAY Contact Toyota Customer Service AT 1-888-270-9371.

#### Consequence

THE Lack OF AN Image IN THE Back-Up Camera Display Increases THE Risk OF A Crash.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
25 Sep 2019



Campaign  
19v678000



Components  
Steering

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive30i, X3 Xdrive30i, and X3 M40i Vehicles, X4 Xdrive30i, and X4 M40i Vehicles. THE Front Axle Swivel Bearings MAY NOT Have Been Properly Heat Treated During Manufacturing, Reducing Their Strength and Possibly Causing Them TO Break.

#### Remedy

BMW HAS Notified Owners and Instructed Them TO NOT Drive Their Vehicles. Dealers Will Replace THE Front Axle Swivel Bearings, Free OF Charge. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

Broken Swivel Bearings CAN Cause A Loss OF Vehicle Control, Increasing THE Risk OF A Crash.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
25 Sep 2019



Campaign  
19v678000



Components  
Suspension:front

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive30i, X3 Xdrive30i, and X3 M40i Vehicles, X4 Xdrive30i, and X4 M40i Vehicles. THE Front Axle Swivel Bearings MAY NOT Have Been Properly Heat Treated During Manufacturing, Reducing Their Strength and Possibly Causing Them TO Break.

#### Remedy

BMW HAS Notified Owners and Instructed Them TO NOT Drive Their Vehicles. Dealers Will Replace THE Front Axle Swivel Bearings, Free OF Charge. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

Broken Swivel Bearings CAN Cause A Loss OF Vehicle Control, Increasing THE Risk OF A Crash.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
19 Mar 2020



Campaign  
20v164000



Components  
AIR Bags

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
19 Mar 2020



Campaign  
20v164000



Components  
Seat Belts:front:buckle Assembly

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
19 Mar 2020



Campaign  
20v164000



Components  
Seat Belts:front:warning  
Light/Devices

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

#### Consequence

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
19 Mar 2020



Campaign  
20v164000



Components  
Seat Belts:pretensioner

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

#### Consequence

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
15 Jun 2020



Campaign  
20v355000



Components  
Steering:linkages:tie ROD Assembly

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019 Z4 Sdrive30i, 2019-2020 330i Xdrive, M340i and M340i Xdrive, 2020 X3M and X4m, and Toyota Supra Vehicles. IN Certain Driving Conditions, Such AS High Temperatures and Rough Road Surfaces, A Steering Gear TIE ROD MAY Become Damaged, Possibly Resulting IN A Fractured TIE Rod.

#### Consequence

A Damaged or Fractured TIE ROD MAY Affect Vehicle Handling and Control, Increasing THE Risk OF A Crash.

#### Remedy

BMW and Toyota Will Notify Owners, and Dealers Will Replace THE Steering Gear TIE Rods, Free OF Charge. THE Recall Began August 14, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417 or Toyota Customer Service AT 1-888-270-9371.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
16 Oct 2019



Campaign  
19v738000



Components  
Steering:rack and Pinion:pinion Shaft

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 BMW X3 M40i and X4 M40i Vehicles. THE Steering Rack Pinion Teeth MAY Break Under Load, Resulting IN A Loss OF Steering Control.

#### Consequence

A Loss OF Steering Control Increases Risk OF A Crash.

#### Remedy

BMW HAS Notified Owners, and Dealers Will Replace THE Steering Gear, Free OF Charge. THE Recall Began October 9, 2019. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Date  
30 Sep 2020



Campaign  
20v601000



Components  
Electrical System:propulsion  
System:traction Battery

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020-2021 530e, 530e Xdrive, 530e Iperformance and X3 Xdrive30e and Mini Cooper Countryman All4 SE, 2020 BMW I8, and 2021 330e, 330e Xdrive, 745le Xdrive and X5 Xdrive45e Vehicles. Debris MAY Have Entered ONE or More OF THE Hybrid Battery Cells During Their Production.

#### Remedy

BMW Will Inspect And, IF Necessary, Replace THE Battery Module Free OF Charge. THE Remedy IS Currently Being Developed. Until THE Remedy IS Completed, Drivers ARE Instructed TO NOT Charge Their Vehicles. Drivers ARE Instructed TO NOT Drive IN Manual Mode, Sport Mode, and TO NOT USE THE Shift Paddles. Owners Were Notified OF THE Safety Risk October 23, 2020. THE Recall Began November 24, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

THE Debris Could Result IN A Short-Circuit, Increasing THE Risk OF Fire or Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
19 Feb 2021



Campaign  
21v096000



Components  
Back Over Prevention: Sensing  
System: Camera

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2021 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, X4 Xdrive30i, X4 M40i, M550i, X4m, X5 Sdrive40i, X5 Xdrive40i, X5 Xdrive50i, X5m, X5 M50i, X7 Xdrive40i, X7 Xdrive50i, X7 M50i, Alpina Xb7, 330i, 330i Xdrive, M340i, M340i Xdrive, and 8 Series Coupe, Convertible and Grand Coupe, 840i, 840i Xdrive, M850i Xdrive, M8, 2020-2021 530e, 530e Xdrive, 330e, 330e Xdrive, 745le, 745le Xdrive, X5 Xdrive45e, X3 Xdrive30e, X6 Sdrive40i, X6 Xdrive40i, X6 Xdrive50i, X6 M50i, X6m, 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 740i, 740li, 740li Xdrive, M760i Drive, M760li Xdrive, 750li Xdrive Alpina, Alpina B7 Xdrive, and 2021 4 Series Coupe 430i, 430i Xdrive, M440i Xdrive Vehicles. When Shifting Into Reverse, A Small Portion OF THE Rearview Image MAY BE Obscured, or THE Screen MAY NOT Illuminate. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rear Visibility."

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect THE Rearview Camera Software and Update IT IF Necessary, Free OF Charge. THE Recall Began April 16, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Missing or Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
19 Feb 2021



Campaign  
21v096000



Components  
Back Over Prevention:software



#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2021 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, X4 Xdrive30i, X4 M40i, M550i, X4m, X5 Sdrive40i, X5 Xdrive40i, X5 Xdrive50i, X5m, X5 M50i, X7 Xdrive40i, X7 Xdrive50i, X7 M50i, Alpina Xb7, 330i, 330i Xdrive, M340i, M340i Xdrive, and 8 Series Coupe, Convertible and Grand Coupe, 840i, 840i Xdrive, M850i Xdrive, M8, 2020-2021 530e, 530e Xdrive, 330e, 330e Xdrive, 745le, 745le Xdrive, X5 Xdrive45e, X3 Xdrive30e, X6 Sdrive40i, X6 Xdrive40i, X6 Xdrive50i, X6 M50i, X6m, 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 740i, 740li, 740li Xdrive, M760i Drive, M760li Xdrive, 750li Xdrive Alpina, Alpina B7 Xdrive, and 2021 4 Series Coupe 430i, 430i Xdrive, M440i Xdrive Vehicles. When Shifting Into Reverse, A Small Portion OF THE Rearview Image MAY BE Obscured, or THE Screen MAY NOT Illuminate. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rear Visibility."

#### Remedy

BMW Will Notify Owners, and Dealers Will Inspect THE Rearview Camera Software and Update IT IF Necessary, Free OF Charge. THE Recall Began April 16, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Missing or Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.safercar.gov](http://www.safercar.gov).



Date  
02 Aug 2021



Campaign  
21v598000



Components  
Engine

#### Summary

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 M340i, M340i Xdrive, 540i, 540i Xdrive, X3 M40i, 2020-2021 X4 M40i, 745le Xdrive, 2019-2021 Z4 M40i, and 2020-2021 Toyota Supra Vehicles. During Engine Start, THE Engine Management Software MAY Cause Loss OF Braking Assist. Full Mechanical Braking (Without Assist) Remains Available.

#### Remedy

Dealers Will Update THE Engine Management Software, Free OF Charge. Owner Notification Letters Were Mailed ON September 17, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

#### Consequence

Loss OF Braking Assist CAN Increase THE Risk OF A Crash.

#### Notes

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [www.nhtsa.gov](http://www.nhtsa.gov).



## Ownership cost

TITLE	YEAR 1	YEAR 2	YEAR 3	YEAR 4	YEAR 5	TOTAL
Depreciation	\$6 899	\$3 312	\$2 898	\$2 622	\$2 346	<b>\$18 077</b>
Insurance	\$2 282	\$2 362	\$2 444	\$2 530	\$2 618	<b>\$12 236</b>
Fuel	\$2 229	\$2 295	\$2 376	\$2 471	\$2 582	<b>\$11 953</b>

TITLE	YEAR 1	YEAR 2	YEAR 3	YEAR 4	YEAR 5	TOTAL
Maintenance	\$1 120	\$1 540	\$1 244	\$1 933	\$1 535	<b>\$7 372</b>
Repair	\$383	\$592	\$665	\$794	\$947	<b>\$3 381</b>
Taxes & fees	\$3 754	\$291	\$263	\$239	\$218	<b>\$4 765</b>
TOTAL FOR 5 YEARS:						<b>\$57 783</b>



## Market value

### MARKET VALUE FOR 2020 BMW X3

<p><b>Below the market</b></p> <hr/> <p>\$39 587 or less</p>	<p><b>Market average</b></p> <hr/> <p><b>\$43 455</b></p>	<p><b>Above the market</b></p> <hr/> <p>\$47 323 or more</p>
--	---	--

Estimates based on 849 similar vehicles sold between 2021-10-15 - 2022-03-18



## NMVTIS consumer access disclaimer

The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and brand history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because some states are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, consumers are strongly encouraged to also obtain an independent vehicle inspection to ensure the vehicle does not have hidden damage. The Approved NMVTIS Data Providers can include vehicle condition data from sources other than NMVTIS.

NMVTIS data includes (as available by those entities required to report to the System):

- Information from participating state motor vehicle titling agencies.



- Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time.
- Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.
- Most recent odometer reading in the state's title record.
- Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.
- Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit [www.vehiclehistory.gov](http://www.vehiclehistory.gov) for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.

## **VIN.doctor disclaimer**

The information used to compile this report is aggregated from various government agencies, non-profit organizations, and industry sources. Access to the National Motor Vehicle Title Information System (NMVTIS) is facilitated through VinAudit Inc., an Approved NMVTIS Data Provider. The accuracy and reliability of the information supplied depends primarily on the reporting sources, and all entities involved in compiling this report accept no liability for any errors or omissions. Furthermore, all warranties, expressed or implied, including any implied warranties of merchantability or fitness for a particular purpose are hereby disclaimed.

Report ID: 5c4a4045e52b0c529a3b5d6588458b107c51f3c4  
Generated: 09 Aug 2022 11:34