



VIN.DOCTOR ЗВІТ ПО ІСТОРІЇ АВТОМОБІЛЯ

2020 BMW X3
VIN 5UXTY3C04LLU69645

Створено: 09 Aug 2022



+ 39 ще



Пробіг

Проблем не знайдено



Пошкодження

Знайдено 3 проблеми



Дані про ДТП

Проблем не знайдено



Утиль

Проблем не знайдено



Угон

Проблем не знайдено



Застава / конфіскація / експорт

Проблем не знайдено



Страхові випадки

Знайдено 10 проблем



Додаткові перевірки авто

Знайдено 2 проблеми



Відгукові кампанії автомобіля

Знайдено 19 проблем



Реєстрації авто

Знайдено 4 записів



Історія продажів

Немає записів



Історія володіння

4 власника



Характеристики авто



Рік випуску

2020



Марка

BMW



Модель

X3



Комплектація

SDrive30i



Двигун

2.0-L-4 DOHC 16V



Країна

United States



Кузов

Немає даних



Рульове управління

Ресчний механізм



АБС
На 4х колесах



Висота
66.00 дюймів



Додаткові місця
Немає даних

Тип палива
Бензин



Довжина
185.90 дюймів



Розхід по трасі
29 миль/галон

Об'єм бака
17.20 галонів



Ширина
74.40 дюймів



Розхід по місту
25 миль/галон

Вага
6000 фунтів



Кількість місць
5



Дилерська ціна нового авто
\$39 515



Роздрібна ціна нового авто
\$41 950



Історія володіння



1 власник

Останні відомі
свідчення одометра:
105 миль

Авто було куплено в:
2020

Орієнтовна тривалість
використання:
1м



2 власник

Останні відомі
свідчення одометра:
3000 миль

Авто було куплено в:
2020

Орієнтовна тривалість
використання:
1р 8м



3 власник

Останні відомі
свідчення одометра:
3670 миль

Авто було куплено в:
2021

Орієнтовна тривалість
використання:
4м



4 власник

Останні відомі
свідчення одометра:
4068 миль

Авто було куплено в:
2022

Орієнтовна тривалість
використання:
Н/Д



Перевірка пробігу

Дійсний

Actual: Пробіг не скручувався і є дійсним.



Проблем не знайдено

Не дійсний

Not actual: Пробіг не є правильним.



Проблем не знайдено

Скручен

Tampering verified: Підтверджено, що показники одометра недійсні (модифіковані).



Проблем не знайдено

Не підлягає реєстрації даних про пробіг

Exempt from odometer disclosure: Транспортний засіб підходить під критерії, що дозволяють міняти дані про власника без реєстрації считаних показників про пробіг.



Проблем не знайдено

Перевищує механічні межі

Exceeds mechanical limits: Показник одометра менше, ніж дійсний пробіг, тобто механический спідометр не відображає дійсний пробіг. Більше 1 мільйона миль, наприклад.



Проблем не знайдено

Може бути скрученим

May be altered: Є передпосилки того, пробіг скручений. Авто потрапив в руки коварних перекупів, які вирішили простими прийомами збільшити вартість автомобіля.



Проблем не знайдено

Замінена одометра

Replaced: Кластер з пробігом замінений.



Проблем не знайдено

Дані на момент оновлення реєстрації

Reading at time of renewal: Показники одометра були считані при поновленні реєстрації.



Проблем не знайдено

Відмінності в показаннях

Discrepancy: Орган, що видавав Свідоцтво про реєстрацію, має причини вважати, що показники одометра не відображають реальний пробіг, тому що не співставляються з попередніми записами про пробіг для даного транспортного засобу.



Проблем не знайдено

Рекомендується узгодження з органом, що видав Свідоцтво про реєстрацію (Title division)

Call title division: Органу, що видав Свідоцтво про реєстрацію, відомо про якісь проблеми з одометром, що не можуть бути відображені / надруковані в Свідоцтві про реєстрацію. Проблему можна обговорити (ручний процес) по офіційному запиту.



Проблем не знайдено

Пробіг перевищує механічний ліміт одометра транспортного засобу

Exceeds mechanical limits rectified. Показник одометра змінений в зв'язку з досягненням механічного ліміту одометра.



Проблем не знайдено



Реєстрації авто

знайдено записів: 4

ПОТОЧНА ІНФОРМАЦІЯ ПРО ТЕХПАСПОРТИ (TITLE)


ДАТА	ШТАТ	ПРОБІГ
22 Apr 2022	CA (Каліфорнія)	4068 миль

ІСТОРІЯ ТЕХПАСПОРТА (TITLE)

ДАТА	ШТАТ	ПРОБІГ
30 Nov 2021	CA (Каліфорнія)	3670 миль
10 Mar 2020	AZ (Арізона)	3000 миль
13 Jan 2020	AZ (Арізона)	105 миль



Історія пробіг / рік



Дані про страхові випадки

знайдено проблем: 10

ДАТА	ОРГАН	ТИП ЗАПISУ	ПОЛОЖЕННЯ	ДЛЯ ЕКСПОРТУ
20 May 2022	Copart Inc. Dallas, TX	Страхові аукціони	Виставлений на продаж	Ні
20 May 2022	Copart Inc. Dallas, TX	Страхові аукціони	Продано	Так
22 Feb 2022	STATE FARM INSURANCE Bloomington, IL	Страхова	Н/Д	Н/Д
22 Feb 2022	IAA WESTCHESTER, IL	Страхові аукціони	Виставлений на продаж	Ні
22 Feb 2022	IAA WESTCHESTER, IL	Страхові аукціони	Продано	Ні
22 Feb 2022	IAA WESTCHESTER, IL	Страхові аукціони	Продано	Ні
24 Jul 2020	IAA WESTCHESTER, IL	Страхові аукціони	Продано	Ні
14 Feb 2020	Copart, Inc. Dallas, TX	Страхові аукціони	Виставлений на продаж	Ні
14 Feb 2020	Copart, Inc. Dallas, TX	Страхові аукціони	Продано	Ні
13 Feb 2020	GEICO CASUALTY COMPANY TUCSON, AZ	Страхова	Н/Д	Н/Д



Дані про угони

✓ Немає записів



Дані про заставу / конфіскацію / експорт

✓ Немає записів



Дані про ДТП

✓ Немає записів



Утиль

✓ Немає записів



Інформація про пошкодження



 1. Передня частина

 2. Ліва сторона

 3. Сторона



Додаткові перевірки авто

знайдено проблем: 2

Salvage (Утиль)

Salvage Damage or Not Specified: Автомобіль, який отримав пошкоджень більше 50% від оціночної вартості і не призначений для відновлення в США, декларується Salvage.



Знайдена проблема

Дата: 22 Apr 2022

Орган: CALIFORNIA (State)

Місцезнаходження: Н/Д



Знайдена проблема

Дата: 10 Mar 2020

Орган: ARIZONA (State)

Місцезнаходження: Н/Д

Rebuilt (Відновлений)

Rebuilt: Автомобіль був з Свідоцтвом про реєстрацію salvage (утиль), але відновлений і пройшов всі інспекції штату. Автомобіль відповідає усім стандартам якості і є безпечним для використання на дорогах.



Знайдена проблема

Дата: 30 Nov 2021

Орган: CALIFORNIA (State)

Місцезнаходження: Н/Д

Пошкодження водою

Flood Damage: Автомобіль був пошкоджений водою. Ступінь пошкоджень невідомий.



Проблем не знайдено

Пошкодження вогнем

Fire Damage: Автомобіль був пошкоджений вогнем. Ступінь пошкоджень невідомий.



Проблем не знайдено

Пошкодження градом

Hail damage: Автомобіль був пошкоджений градом.



Проблем не знайдено

Пошкодження солоною водою

Salt water damage: Автомобіль був пошкоджений солоною водою. Ступінь пошкоджень невідомий.



Проблем не знайдено

Вандалізм

Vandalism: пошкодження в результаті акту вандалізма: подряпини, покраска авто з балончика, пошкодження авто бітою, камінням тощо.



Проблем не знайдено

Каркіт

Kit: Автомобиль, переделанный в каркіт. Використане оригінальне шасі, але кузов замінено. Номери кузова і рами можуть не співпадати.



Проблем не знайдено

Авто на розбор

Dismantled: Автомобіль може продаватись лише як запчастини. Використання на дорогах заборонене.



Проблем не знайдено

Junk (утиль)

Junk: Автомобіль списаний з Свідоцтвом про реєстрацію (title) з приміткою Junk. Кілька штатів в США видають Свідоцтво з приміткою junk (наприклад, штати Missouri, Florida). Не призначений для використання на дорогах США. По законодавству США такий автомобіль не підлягає відновленню і повторній реєстрації. Схожі типи Свідоцтв про реєстрацію: non-repairable, scrapped или destroyed.



Проблем не знайдено

Reconstructed (Відновлений) Reconstructed: Автомобіль, який був відновлений шляхом видалення, добавлення чи заміни основних несучих частин авто. Приклад, заднє крило вирізане і переварено.	 Проблем не знайдено
Демо-авто Test Vehicle: Автомобиль був використаний в якості демо-авто для тестових заїздів і демонстрацій на автомобільних виставках.	 Проблем не знайдено
Refurbished (Оновлений) Refurbished: рама или кузов автомобіля був оновлені, в результаті чого збільшена вартість авто.	 Проблем не знайдено
ДТП Collision: Автомобіль був пошкоджений в ДТП.	 Проблем не знайдено
Salvage Retention (Удержание) Salvage Retention: Автомобиль отримав статус утиль (salvage), але був викуплений і утриманий власником авто.	 Проблем не знайдено
Використання в таксі Prior Taxi: Автомобіль використовувався в таксі.	 Проблем не знайдено
Автопарк поліції Prior Police: Автомобіль був в автопарку поліції.	 Проблем не знайдено
Зараз використовується в таксі Original Taxi: Автомобіль використовується в таксі.	 Проблем не знайдено
Зараз використовується в поліції Original Police: Автомобіль використовується в автопарку поліції.	 Проблем не знайдено
Remanufactured Remanufactured: Автомобіль був відновлений виробником з дотриманням всіх стандартів якості.	 Проблем не знайдено
Сірий ринок Gray Market: Автомобіль був випущений для інших країн, не США, але завезений в США як сірий імпорт.	 Проблем не знайдено
Повернення по гарантії Warranty Return: Автомобіль був викуплений виробником по гарантії.	 Проблем не знайдено
Античний авто Antique: Автомобілю більше 50 років.	 Проблем не знайдено
Класичний авто Classic: Автомобілю більше 20 років.	 Проблем не знайдено
Використання в агро-сервісі Agricultural Vehicle: Автомобіль призначався для використання в агро-сервісі.	 Проблем не знайдено

Використання для заміру лічильників

Проблем не знайдено

Logging Vehicle: Автомобіль використовувався в державних органах для заміру лічильників. Приклад, газова компанія використовує автомобіль, які використовують для об'їзду міста ібору даних газових лічильників.

Міський род

Проблем не знайдено

Street Rod: Автомобіль був дороблений. Тюнинг.

Заміна VIN

Проблем не знайдено

Vehicle Contains Reissued VIN: Заміна VIN на кузові авто. VIN номер не змінювався.

Репліка

Проблем не знайдено

Replica: Автомобіль перероблений, щоб візуально нагадувати інше авто.

Повна втрата

Проблем не знайдено

Totaled: Вартість ремонту більше 100% від оціночної вартості авто.

Утримання авто власником

Проблем не знайдено

Owner Retained: Автомобіль задекларований повною втратою, але власник авто вирішив залишити авто собі.

Bond Posted

Проблем не знайдено

Bond Posted: Страхова компанія випустила облігацію на транспортний засіб, так як власник авто не може бути доведений. Таким чином, транспортний засіб підлягає продажу і реєстрації. Даний тип сертифіката не використовується після 17 січня 2003.

Копія документів

Проблем не знайдено

Memorandum Copy: Свідцтво про реєстрацію – факсимільна копія. Не оригінал.

Лише на запчастини

Проблем не знайдено

Parts Only: Автомобіль можна використовувати тільки на запчастини. Не призначений для відновлення.

Знайдено після угону

Проблем не знайдено

Recovered Theft: Автомобіль з Свідцтвом про реєстрацію (title) з приміткою утиль по причині угону. Проведена інспекція, що дозволяє використовувати транспортний засіб на дорогах.

Undisclosed Lien

Проблем не знайдено

Undisclosed Lien: Автомобіль потрапив в юрисдикцію органу реєстрації з юрисдикції, яка не розкриває даних про власника транспортного засобу по техпаспорту. Уповноважений орган може видати новий техпаспорт без даного сертифіката, якщо в встановлені строки не буде заявлено іншого власника даного засобу. Даний тип сертифіката не використовується після 17 січня 2003 року.

**Зміна власника після
попереднього статусу Owner
Retained**

Prior owner retained: Транспортний засіб мав сертифікат типу "owner retained" і був проданий. Техпаспорт нового власника буде мати даний тип сертифіката.

✓ Проблем не знайдено

**Дефект невідповідності не
виправлений**

Vehicle Non-conformity Uncorrected: По даному транспортному засобу був зроблений звіт про невідповідність, що не впливає на безпеку, і ця невідповідність не була ліквідована.

✓ Проблем не знайдено

**Дефект невідповідності
ліквідований**

Vehicle Non-conformity Corrected: По даному транспортному засобу виробнику був даний звіт про несправність, що не впливає на безпеку і несправність була ліквідована.

✓ Проблем не знайдено

**Несправність, що впливає на
безпеку, не ліквідована**

Vehicle Safety Defect Uncorrected: По даному транспортному засобу виробнику був зроблений звіт про несправність, що впливає на безпеку і ця несправність не була ліквідована.

✓ Проблем не знайдено

**Несправність, що впливає на
безпеку транспортного
средства, ліквідована**

Vehicle Safety Defect Corrected: По даному транспортному засобу виробнику був зроблений звіт про несправність, що впливає на безпеку и несправність була ліквідована.

✓ Проблем не знайдено

Заміна VIN

VIN Replaced: VIN номер був замінений на новий VIN номер.

✓ Проблем не знайдено

Серый рынок: Non-compliant

Gray Market: Non-compliant: Автомобіль був випущений для інших країн, ніж США, але завезений в США посередництвом сірого імпорту. Не призначений для використання в США, так як не відповідає федеральним вимогам.

✓ Проблем не знайдено

Серый рынок: Compliant

Gray Market: Compliant: Автомобіль був випущений для інших країн, ніж США, але завезений в США посередництвом сірого імпорту. Може використовуватись в США, так як відповідає федеральним вимогам.

✓ Проблем не знайдено

Lemon-Law Buyback: Лемон

Manufacturer Buy Back: Автомобіль був викуплений у власника автовиробником через серйозну несправність. Наприклад, в власника не працює кондиціонер. Виробник ремонтує тричі авто, але проблема повторюється. Виробник викупує авто у власника і декларує авто Lemon-Law Buyback.

✓ Проблем не знайдено

Орендний авто

Former Rental: Авто використовувалось в орендному парку.

✓ Проблем не знайдено

Salvage: Угон

Salvage: Stolen. Автомобіль списаний в утиль по причині угона. Власник авто отримав компенсацію за автомобіль. Автомобіль списується страховою компанією і продається на страховому аукціоні.



Проблем не знайдено

Salvage: Другі причини, не угон чи ДТП

Salvage: Reasons Other Than Damage or Stolen. Автомобіль списаний в утиль по іншій причині, ніж угон чи ДТП. Рідке списання. Наприклад, автомобіль, залишений на дорозі.



Проблем не знайдено

Зареєстроване пошкодження

Disclosed damage: Автомобіль був в серйозному ДТП. По закону штату необхідно вказувати пошкодження в Свідоцтві про реєстрацію.



Проблем не знайдено

Раннее Non-Repairable / Відновлений

Prior Non-Repairable / Repaired: Автомобіль відновлений з non-repairable.



Проблем не знайдено

Роздавлений

Crushed: Рама і кузов автомобіля знищені.



Проблем не знайдено

Признаний небезпечним для навколишнього середовища

Hazardous: Судом було визначено, що автомобіль є небезпечним для оточуючих. Можливі причини: вибухові і легкозаймисті речовини, вірус, зомбі-апокаліпсис.



Проблем не знайдено

Тільки на експорт

Автомобіль, який був списаний в утиль, можливо тільки експортувати за межі США. Не призначений для повторної реєстрації та експлуатації на території США.



Проблем не знайдено



Історія продажів авто

АВТО ДИЛЕРИ, ЕВАУ, И Т.Д. - 0



Немає записів

ПРОДАЖІ З АУКЦІОНІВ СТРАХОВИХ КОМПАНІЙ - 20



23 Mar 2020



всі фото

Номер лота: [30597370](#)

ПРОДАНО

Пошкодження: Передня частина

\$4 450

 29 Jul 2020



всі фото

Номер лота: 28141528 **НОВИЙ ЛОТ**

НЕ ПРОДАНО

Пошкодження: Передня частина, Ліва сторона

\$11 250

 05 Aug 2020



всі фото

Номер лота: 28141528

ПРОДАНО

Пошкодження: Передня частина, Ліва сторона

\$12 475

 28 Apr 2022



всі фото

Номер лота: 32497081 **НОВИЙ ЛОТ**

НЕ ПРОДАНО

Пошкодження: Передня частина, Ліва сторона

\$10 050

 05 May 2022



всі фото

Номер лота: 32497081

ПРОДАНО

Пошкодження: Передня частина, Ліва сторона

\$10 025



31 May 2022



всі фото

Номер лота: [46625632](#) **НОВИЙ ЛОТ**

НЕ ПРОДАНО

Пошкодження: Передня частина, Сторона

\$18 800



03 Jun 2022



всі фото

Номер лота: [46625632](#)

НЕ ПРОДАНО

Пошкодження: Передня частина, Сторона

\$18 800



06 Jun 2022



всі фото

Номер лота: [46625632](#)

НЕ ПРОДАНО

Пошкодження: Передня частина, Сторона

\$19 000



09 Jun 2022



всі фото

Номер лота: [46625632](#)

НЕ ПРОДАНО

Пошкодження: Передня частина, Сторона

\$19 000



13 Jun 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 500



20 Jun 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 700



05 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 300



08 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 300



11 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 100



14 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 100



18 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$17 600



21 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$17 600



25 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 400



28 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

НЕ ПРОДАНО

\$18 400



29 Jul 2022



всі фото

Номер лота: [46625632](#)

Пошкодження: Передня частина, Сторона

ПРОДАНО

\$20 000



Відгукові кампанії автомобіля

знайдено проблем: 19



Дата
30 Sep 2020



Кампанія
20v598000



Компоненти
Back Over Prevention: Sensing
System: Camera

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020-2021 X3 Sdrive 30i, X3 Xdrive 30i, X3M 40i, X3 Xdrive 30e, X4 Xdrive 30i, X4M 40i, 530i, 540i, 540i Xdrive, M550i Xdrive, M5, 550e, 550e Xdrive, and 550e lperformance Vehicles. A Small Portion OF THE Rearview Image MAY BE Slightly Obscured. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rear Visibility."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect And, IF Necessary, Program THE Rearview Camera With Updated Software. THE Recall Began November 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата

18 Aug 2020



Кампанія

20v490000



Компоненти

Electrical System:12v/24v/48v Battery

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2021 330e and X5 Xdrive45e, 2020-2021 X3 Xdrive30e, and 2020 Mini Countryman SE All4 Vehicles. Loose Welding Beads MAY Form A Conductive Path Between THE Hybrid Battery Cells Which Could Lead TO A Short-Circuit.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect And, IF Necessary, Replace THE Battery Modules, Free OF Charge. BMW Issued Owners AN Interim Notification ON October 16, 2020. Although Potentially Affected BMW Owners Received Interim Owner Notification Letters, All Potentially Affected BMW Owner Vehicles Have Been Remedied; Therefore, BMW Final Owner Notification Letters Will NOT BE Necessary. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

A Short-Circuited Hybrid Battery MAY Increase THE Risk OF A Fire.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата

18 Mar 2020



Кампанія

20v152000



Компоненти

Electrical System: Instrument Cluster/Panel

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2020 X4 Xdrive30i and X4 M40i, and 2018-2020 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, and X3M Vehicles. THE Instrument Panel Casing MAY NOT Have Been Tightened Properly TO THE Passenger AIR Bag.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Replace THE Instrument Panel Casing, Free OF Charge. THE Recall Began MAY 15, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IN THE Event OF A Crash Necessitating AIR BAG Deployment, THE AIR BAG Could Damage THE Instrument Panel and Cause Small Pieces OF THE Panel TO Strike THE Driver or Other Occupants, Increasing THE Risk OF Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата

18 Mar 2020



Кампанія

20v152000



Компоненти

AIR Bags:frontal:passenger Side:inflator Module

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2020 X4 Xdrive30i and X4 M40i, and 2018-2020 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, and X3M Vehicles. THE Instrument Panel Casing MAY NOT Have Been Tightened Properly TO THE Passenger AIR Bag.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Replace THE Instrument Panel Casing, Free OF Charge. THE Recall Began MAY 15, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IN THE Event OF A Crash Necessitating AIR BAG Deployment, THE AIR BAG Could Damage THE Instrument Panel and Cause Small Pieces OF THE Panel TO Strike THE Driver or Other Occupants, Increasing THE Risk OF Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
29 Jul 2020



Кампанія
20v443000



Компоненти
Electrical System:software

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive40i, X3 Xdrive40i and X3m40i Vehicles. These Vehicles Were NOT Programmed With Rearview Camera Software During Assembly, Therefore, When THE Transmission IS Shifted TO Reverse, A Rearview Image IS NOT Displayed. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rearview Mirrors."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Program THE Affected Vehicles With Rearview Camera Software, Free OF Charge. THE Recall Began August 14, 2020. All Vehicles Have Been Remedied AS OF November 9, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

AN Inoperative Rearview Camera Display CAN Increase THE Risk OF A Crash When Reversing.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
29 Jul 2020



Кампанія
20v443000



Компоненти
Back Over Prevention: Sensing System: Camera

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive40i, X3 Xdrive40i and X3m40i Vehicles. These Vehicles Were NOT Programmed With Rearview Camera Software During Assembly, Therefore, When THE Transmission IS Shifted TO Reverse, A Rearview Image IS NOT Displayed. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard Number 111, "rearview Mirrors."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Program THE Affected Vehicles With Rearview Camera Software, Free OF Charge. THE Recall Began August 14, 2020. All Vehicles Have Been Remedied AS OF November 9, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

AN Inoperative Rearview Camera Display CAN Increase THE Risk OF A Crash When Reversing.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
27 Sep 2019



Кампанія
19v684000



Компоненти
Back Over Prevention: Sensing System: Camera

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2018 540d, 2018-2020 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 530e, 530e Xdrive, X3 Sdrive, X3 Xdrive, X3 M40i, X3 M, and 2019-2020 X4 Xdrive, X4 M40i, X4 M, X7 Xdrive, X7 M50i, 740li, 740li Xdrive, 750li, 750li Xdrive, 8 Series Convertible and Coupe 840i, 840i Xdrive, M850i Xdrive, X5 Sdrive, X5 Xdrive, X5 M50i, X6 Xdrive, X6 M50i, 330i, 330i Xdrive, M340i, M340i Xdrive, Z4 Sdrive, Z4 M40i, 740le Xdrive and 745le Xdrive, 2018-2019 640i Xdrive Gran Turismo and Rolls-royce Phantom, 2019 M850i Xdrive Gran Coupe and Rolls-royce Cullinan and 2020 Toyota Supra Vehicles. THE Back-up Camera and Display Settings CAN BE Adjusted Such That THE Rear View Image IS NO Longer Visible and THE System Will Retain That Setting THE Next Time THE Vehicle IS Placed IN Reverse. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rearview Mirrors."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Update THE Back-Up Camera Software, Free OF Charge. THE Recall Began November 8, 2019. Owners MAY Contact BMW Customer Service AT 1-800-525-7417 or Rolls-royce AT 1-877-877-3735. Toyota Owners MAY Contact Toyota Customer Service AT 1-888-270-9371.

Ризики

THE Lack OF AN Image IN THE Back-Up Camera Display Increases THE Risk OF A Crash.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
25 Sep 2019



Кампанія
19v678000



Компоненти
Steering

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive30i, X3 Xdrive30i, and X3 M40i Vehicles, X4 Xdrive30i, and X4 M40i Vehicles. THE Front Axle Swivel Bearings MAY NOT Have Been Properly Heat Treated During Manufacturing, Reducing Their Strength and Possibly Causing Them TO Break.

Вжитий захід

BMW HAS Notified Owners and Instructed Them TO NOT Drive Their Vehicles. Dealers Will Replace THE Front Axle Swivel Bearings, Free OF Charge. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

Broken Swivel Bearings CAN Cause A Loss OF Vehicle Control, Increasing THE Risk OF A Crash.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
25 Sep 2019



Кампанія
19v678000



Компоненти
Suspension:front

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Sdrive30i, X3 Xdrive30i, and X3 M40i Vehicles, X4 Xdrive30i, and X4 M40i Vehicles. THE Front Axle Swivel Bearings MAY NOT Have Been Properly Heat Treated During Manufacturing, Reducing Their Strength and Possibly Causing Them TO Break.

Вжитий захід

BMW HAS Notified Owners and Instructed Them TO NOT Drive Their Vehicles. Dealers Will Replace THE Front Axle Swivel Bearings, Free OF Charge. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

Broken Swivel Bearings CAN Cause A Loss OF Vehicle Control, Increasing THE Risk OF A Crash.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
19 Mar 2020



Кампанія
20v164000



Компоненти
AIR Bags

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Дата
19 Mar 2020



Кампанія
20v164000



Компоненти
Seat Belts:front:buckle Assembly

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO [Www.safercar.gov](http://www.safercar.gov).



Дата
19 Mar 2020



Кампанія
20v164000



Компоненти
Seat Belts:front:warning
Light/Devices

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

Ризики

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
19 Mar 2020



Кампанія
20v164000



Компоненти
Seat Belts:pretensioner

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 X3 Xdrive30e, X4 Xdrive30i, X4 M40i, X4m, 330i, 330i Xdrive, M340i, 840i Gran Coupe, 840i Xdrive Gran Coupe, M850i Xdrive Gran Coupe, M8 Gran Coupe, X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, and 840i Xdrive Convertible Vehicles. THE Sensors IN THE Front Seat Belt Buckles MAY Inaccurately Detect A Belted Occupant AS Unbelted, Possibly Causing THE AIR BAG and Seat Belt Pretensioners TO Deploy Improperly IN THE Event OF A Crash.

Ризики

IF THE AIR BAG And/Or Seat Belt Pretensioners Deploy Improperly IN THE Event OF A Crash, There IS AN Increased Risk OF Injury TO THE Driver and Front Passenger.

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect and Replace THE Front Seat Belt Buckles, AS Necessary, Free OF Charge. THE Recall Began MAY 18, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
15 Jun 2020



Кампанія
20v355000



Компоненти
Steering:linkages:tie ROD Assembly

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019 Z4 Sdrive30i, 2019-2020 330i Xdrive, M340i and M340i Xdrive, 2020 X3M and X4m, and Toyota Supra Vehicles. IN Certain Driving Conditions, Such AS High Temperatures and Rough Road Surfaces, A Steering Gear TIE ROD MAY Become Damaged, Possibly Resulting IN A Fractured TIE Rod.

Ризики

A Damaged or Fractured TIE ROD MAY Affect Vehicle Handling and Control, Increasing THE Risk OF A Crash.

Вжитий захід

BMW and Toyota Will Notify Owners, and Dealers Will Replace THE Steering Gear TIE Rods, Free OF Charge. THE Recall Began August 14, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417 or Toyota Customer Service AT 1-888-270-9371.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
16 Oct 2019



Кампанія
19v738000



Компоненти
Steering:rack and Pinion:pinion Shaft

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 BMW X3 M40i and X4 M40i Vehicles. THE Steering Rack Pinion Teeth MAY Break Under Load, Resulting IN A Loss OF Steering Control.

Ризики

A Loss OF Steering Control Increases Risk OF A Crash.

Вжитий захід

BMW HAS Notified Owners, and Dealers Will Replace THE Steering Gear, Free OF Charge. THE Recall Began October 9, 2019. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
30 Sep 2020



Компанія
20v601000



Компоненти
Electrical System:propulsion
System:traction Battery

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020-2021 530e, 530e Xdrive, 530e Iperformance and X3 Xdrive30e and Mini Cooper Countryman All4 SE, 2020 BMW I8, and 2021 330e, 330e Xdrive, 745le Xdrive and X5 Xdrive45e Vehicles. Debris MAY Have Entered ONE or More OF THE Hybrid Battery Cells During Their Production.

Вжитий захід

BMW Will Inspect And, IF Necessary, Replace THE Battery Module Free OF Charge. THE Remedy IS Currently Being Developed. Until THE Remedy IS Completed, Drivers ARE Instructed TO NOT Charge Their Vehicles. Drivers ARE Instructed TO NOT Drive IN Manual Mode, Sport Mode, and TO NOT USE THE Shift Paddles. Owners Were Notified OF THE Safety Risk October 23, 2020. THE Recall Began November 24, 2020. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

THE Debris Could Result IN A Short-Circuit, Increasing THE Risk OF Fire or Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
19 Feb 2021



Компанія
21v096000



Компоненти
Back Over Prevention: Sensing
System: Camera

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2021 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, X4 Xdrive30i, X4 M40i, M550i, X4m, X5 Sdrive40i, X5 Xdrive40i, X5 Xdrive50i, X5m, X5 M50i, X7 Xdrive40i, X7 Xdrive50i, X7 M50i, Alpina Xb7, 330i, 330i Xdrive, M340i, M340i Xdrive, and 8 Series Coupe, Convertible and Grand Coupe, 840i, 840i Xdrive, M850i Xdrive, M8, 2020-2021 530e, 530e Xdrive, 330e, 330e Xdrive, 745le, 745le Xdrive, X5 Xdrive45e, X3 Xdrive30e, X6 Sdrive40i, X6 Xdrive40i, X6 Xdrive50i, X6 M50i, X6m, 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 740i, 740li, 740li Xdrive, M760i Drive, M760li Xdrive, 750li Xdrive Alpina, Alpina B7 Xdrive, and 2021 4 Series Coupe 430i, 430i Xdrive, M440i Xdrive Vehicles. When Shifting Into Reverse, A Small Portion OF THE Rearview Image MAY BE Obscured, or THE Screen MAY NOT Illuminate. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rear Visibility."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect THE Rearview Camera Software and Update IT IF Necessary, Free OF Charge. THE Recall Began April 16, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Missing or Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
19 Feb 2021



Компанія
21v096000



Компоненти
Back Over Prevention:software

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2019-2021 X3 Sdrive30i, X3 Xdrive30i, X3 M40i, X3m, X4 Xdrive30i, X4 M40i, M550i, X4m, X5 Sdrive40i, X5 Xdrive40i, X5 Xdrive50i, X5m, X5 M50i, X7 Xdrive40i, X7 Xdrive50i, X7 M50i, Alpina Xb7, 330i, 330i Xdrive, M340i, M340i Xdrive, and 8 Series Coupe, Convertible and Grand Coupe, 840i, 840i Xdrive, M850i Xdrive, M8, 2020-2021 530e, 530e Xdrive, 330e, 330e Xdrive, 745le, 745le Xdrive, X5 Xdrive45e, X3 Xdrive30e, X6 Sdrive40i, X6 Xdrive40i, X6 Xdrive50i, X6 M50i, X6m, 530i, 530i Xdrive, 540i, 540i Xdrive, M550i Xdrive, M5, 740i, 740li, 740li Xdrive, M760i Drive, M760li Xdrive, 750li Xdrive Alpina, Alpina B7 Xdrive, and 2021 4 Series Coupe 430i, 430i Xdrive, M440i Xdrive Vehicles. When Shifting Into Reverse, A Small Portion OF THE Rearview Image MAY BE Obscured, or THE Screen MAY NOT Illuminate. AS Such, These Vehicles Fail TO Comply With THE Requirements OF Federal Motor Vehicle Safety Standard (Fmvss) Number 111, "rear Visibility."

Вжитий захід

BMW Will Notify Owners, and Dealers Will Inspect THE Rearview Camera Software and Update IT IF Necessary, Free OF Charge. THE Recall Began April 16, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

IF THE Driver Relies ON Only THE Rearview Camera Image, THE Missing or Reduced Rearview Image View CAN Increase THE Risk OF A Crash or Injury.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.safercar.gov.



Дата
02 Aug 2021



Кампанія
21v598000



Компоненти
Engine

Опис

BMW OF North America, LLC (Bmw) IS Recalling Certain 2020 M340i, M340i Xdrive, 540i, 540i Xdrive, X3 M40i, 2020-2021 X4 M40i, 745le Xdrive, 2019-2021 Z4 M40i, and 2020-2021 Toyota Supra Vehicles. During Engine Start, THE Engine Management Software MAY Cause Loss OF Braking Assist. Full Mechanical Braking (Without Assist) Remains Available.

Вжитий захід

Dealers Will Update THE Engine Management Software, Free OF Charge. Owner Notification Letters Were Mailed ON September 17, 2021. Owners MAY Contact BMW Customer Service AT 1-800-525-7417.

Ризики

Loss OF Braking Assist CAN Increase THE Risk OF A Crash.

Примітки

Owners MAY Also Contact THE National Highway Traffic Safety Administration Vehicle Safety Hotline AT 1-888-327-4236 (Tty 1-800-424-9153), or GO TO www.nhtsa.gov.



Вартість експлуатації

НАЙМЕНУВАННЯ	PIK 1	PIK 2	PIK 3	PIK 4	PIK 5	ВСЬОГО
Амортизація	\$6 899	\$3 312	\$2 898	\$2 622	\$2 346	\$18 077
Страхування	\$2 282	\$2 362	\$2 444	\$2 530	\$2 618	\$12 236
Паливо	\$2 229	\$2 295	\$2 376	\$2 471	\$2 582	\$11 953

НАЙМЕНУВАННЯ	РІК 1	РІК 2	РІК 3	РІК 4	РІК 5	ВСЬОГО
Технічне обслуговування	\$1 120	\$1 540	\$1 244	\$1 933	\$1 535	\$7 372
Ремонт	\$383	\$592	\$665	\$794	\$947	\$3 381
Податки і збори	\$3 754	\$291	\$263	\$239	\$218	\$4 765
ВСЬОГО ЗА 5 РОКІВ:						\$57 783



Ринкова вартість

РИНКОВА ВАРТІСТЬ 2020 BMW X3

Нижче ринку \$39 587 або менше	Середня ринкова вартість \$43 455	Вище ринку \$47 323 або більше
---	---	---

Оцінки засновані на 849 аналогічних авто, проданих у період 2021-10-15 - 2022-03-18



Письмова відмова від відповідальності NMVTIS

Національна система інформації про плаво власності на автотранспортні засоби (NMVTIS) - це електронна система, яка містить інформацію про певні автомобілі, що зареєстровані в Сполучених Штатах Америки. NMVTIS призначена для того, щоб слугувати надійним джерелом по типу Свідоцтво про реєстрацію (title) автомобілів, але вона не містить детальної інформації про історію ремонту автомобіля.

Страхові компанії і страхові автомобільні аукціони в усіх штатах зобов'язані у відповідності з федеральним законом регулярно повідомляти інформацію в NMVTIS. В той же час NMVTIS не містить інформації про всі транспортні засоби в США, тому що дані надаються різними штатами в різні строки; деякі штати обновляють дані NMVTIS в режимі реального часу, тобто по факту проведення транзакції, в той час як інші штати здійснюють оновлення не так часто, інколи раз в декілька днів.

Інформація про попереднє серйозне пошкодження транспортного засобу може не бути включеною в систему, якщо автомобіль не був зафіксований страховою компанією (чи іншим авторизованим органом) як "total loss", тобто повну втрату. І навпаки, інколи з певних причин страхова компанія заявляє транспортний засіб як "total loss", хоча по техпаспорту транспортний засіб не визначений як «утиль».

Звіт про історію транспортного засобу НЕ МОЖНА ТРАКТУВАТИ як заміна незалежної інспекції транспортного засобу. Перед прийняттям рішення про покупку транспортного засобу покупцю наполегливо рекомендується придбати незалежну інспекцію транспортного засобу для того, щоб пересвідчитись в відсутності скритих пошкоджень.

Довірені джерела NMVTIS можуть також містити дані про стан транспортного засобу з інших джерел, не NMVTIS.

NMVTIS дані містять наступну інформацію:

- Інформація від державних органів, що беруть участь, і які займаються видачею Свідоцтв про реєстрацію (titles).
- Інформацію про автомобілі, автобуси, вантажівки, мотоцикли, рекреаційні транспортні засоби, будинки на колесах і тракторах. NMVTIS не має даних по комерційних транспортних засобах, якщо ці транспортні засоби не занесені в центральну базу даних записів про видачу Свідоцтв про реєстрацію (titles) штату (в деяких штатах такі транспортні засоби підлягають реєстрації в окремих транспортних агенствах), хоча такі дані можуть бути додані пізніше.
- Інформацію про типи Свідоцтв про реєстрації (salvage, junk, non-repairable тощо.). Типи Свідоцтв про реєстрацію і визначення можуть відрізнятися залежно від штата, але можуть містити важливу інформацію про стан чи попереднє використання транспортного засобу.
- Самые последние данные о показателях пробега, зафиксированные в техпаспорте.
- Інформацію від страхових компаній, свалок, страхових авто аукціонів, які зобов'язані у відповідності з нормами закону повідомляти дані з 31 березня 2009 року. Ця інформація містить дані про реєстрацію транспортного засобу страховою компанією як total loss.
- Інформацію від дилерів і компаній, які отримують "cash for clunker" (гроші за автохлам), продані у відповідності до умов програми Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Користувачам рекомендується відвідати сайт www.vehiclehistory.gov для отримання детальної інформації по інтерпретації даних системи, уточнення термінології, що використовується різними джерелами в реєстрації транспортних засобів в базі.

Письмова відмова від відповідальності VIN.DOCTOR

В підготовці даного звіту використовувалась інформація, зібрана з різних джерел, в т.ч. державних агентств, неурядових організацій, онлайн ресурсів, страхових аукціонів і інших баз даних. Доступ до даних National Motor Vehicle Title Information System (NMVTIS) здійснюється через партнера, що має статус Approved NMVTIS Data Provider. Точність і надійність інформації залежить від точності даних в первинному джерелі та від якості роботи всіх організацій, що зацікавлені в підготовці звіту. Таким чином, VIN.DOCTOR є агрегатором даних, не несе відповідальності і не дає жодних гарантій точності даних і доцільності використання цих даних для певних комерційних цілей користувачів.

ID звіту: 5c4a4045e52b0c529a3b5d6588458b107c51f3c4
Створено: 09 Aug 2022 11:34